




LOC/DME I-PWM 109.9 Chan 36	APP CRS 110°	Rwy Idg 7200 TDZE 76 Apt Elev 76
---	------------------------	---

ILS RWY 11 (SA CAT I)
PORTLAND INTL JETPORT (PWM)

T A Procedure NA when control tower closed. Requires specific OPSPEC, MSPEC, or LOA approval and use of HUD to DH.	ALSIF-2 A		MISSED APPROACH: Climb to 600 then climbing right turn to 3000 direct ENE VOR/DME and hold.		
ATIS 119.05	PORTLAND APP CON ★ 119.75 269.35	PORTLAND TOWER ★ 120.9 0 (CTAF) 257.8	GND CON 121.9	CLNC DEL 121.9	UNICOM 122.95



SA CATEGORY I ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED

TDZ/CL Rwy 11 0

MIRL Rwy 18-36 0

HIRL Rwy 11-29 0

REIL Rwy 18 and 36 0