

VORTAC RQZ	APP CRS	Rwy Idg	N/A
112.2	043°	TDZE	N/A
Chan 59		Apt Elev	764

VOR-B

HUNTSVILLE EXEC TOM SHARP JR FLD (MDQ)

DME required.	MISSED APPROACH: Climbing left turn to 3000 direct RQZ VORTAC and hold.
	

AWOS-3PT 120.0	HUNTSVILLE APP CON★ 125.6 354.1	GCO 121.725	UNICOM 123.0 (CTAF) 0
--------------------------	---	-----------------------	--

