


**SCAMMON BAY** (SCM)(PACM)    0 N    UTC-9(-8DT)    N61°50.67' W165°34.43'  
22    B    NOTAM FILE SCM  
RWY 10-28: 3001X75 (DIRT)    MIRL

**BETHEL**  
L-3B  
IAP

**RWY 28:** Brush. Rgt t/c.  
**SERVICE:**    LGT ACTVT MIRL Rwy 10-28 and rotating bcn—CTAF.  
**AIRPORT REMARKS:** Unattended. Rwy condition not monitored, recommend visual inspection prior to using. Birds on rwy. Cold temperature airport. Altitude correction required at or below -21C. Rwy 10-28 road used to cross rwy to river. Be alert: gusty crosswinds common. Rwy edges soft and sloughing towards tundra. Rwy 28 safety area soft and contains large rocks; only 75 ft usable. Rwy 10-28 soft durg spring breakup, after rains and durg extreme high tides. Wind indicators unreliable. Rwy 10-28 mkd with cones and reflective thr panels. Rwy 10 thr panels damaged or missing.  
**AIRPORT MANAGER:** (907) 543-2498  
**WEATHER DATA SOURCES:** AWOS-3P 118.425 (907) 558-5501. (WX CAM)  
**COMMUNICATIONS:** CTAF/UNICOM 123.0  
Ⓡ **ANCHORAGE CENTER APP/DEP CON** 124.5  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE HPB.  
**HOOPER BAY (H) (H) VOR/DME** 115.2    HPB    Chan 99    N61°30.86' W166°08.07'    026° 25.5 NM to fld. 15/13E.  
VOR unusable:  
358°-013° byd 22 NM blo 3,500'  
DME unusable:  
358°-013° byd 22 NM blo 3,500'  
**COMM/NAV/WEATHER REMARKS:** For a toll free call to Kenai FSS dial 1-866-864-1737.



**SCOOTERS LANDING STRIP** (See STERLING on page 230)

**SCOTTS** (See NORTH POLE on page 183)

**SECLUDED LAKE** (See TALKEETNA on page 233)

**SELAWIK**

**ROLAND NORTON MEML AIRSTRIP** (8AK3) PVT    12 S    UTC-9(-8DT)    N66°45.96' W160°09.17'  
360    NOTAM FILE  
RWY 02-20: 3000X70 (GRVL)

**NOME**  
L-4I

**RWY 20:** Mtn.  
**AIRPORT REMARKS:** Unattended. Rwy slopes downhill at 3% toward west. Rwy condition not monitored; recommend visual inspection prior to landing. Rwy marked with red and white 55 gallon drums.  
**COMMUNICATIONS:** CTAF 122.7  
**COMM/NAV/WEATHER REMARKS:** For LC to Kotzebue FSS dial 907-442-3310. For a toll free call to Kotzebue FSS dial 1-800-478-7460. For a toll free call to Fairbanks FSS dial 1-866-248-6516.