MINNESOTA

CLEAR LAKE LEADERS CLEAR LAKE (8Y6) 2 E UTC-6(-5DT) N45°26.66' W93°58.27' TWIN 990 NOTAM FILE PNM RWY 18-36: H3000X150 (ASPH-TURF) RWY 18: Crops. RWY 36: Trees. SERVICE: S4 FuEL 100LL AIRPORT REMARKS: Attended 1400Z‡-dusk. Fuel after hrs ctc arpt manager. There are several bare spots along the centure the rwy. Rwy 18-36 and dsplcd thresholds marked with yellow cones. Rwy 18-36 sfc uneven and rough with loose AIRPORT MANAGER: 612-743-2294 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.	er of
	IN BAY L-14I IAP

COOK CO N47°50.40′ W90°23.13′ NOTAM FILE CKC. NDB (MHW) 358 CKC at Grand Marais/Cook Co. 1762/1W. GREEN BAY L—14I