 890 TPA—See Remarks NOTAM FILE ICT RWY 16-34: 3030X80 (TURF) LIRL(NSTD) RWY 34: Tree. SERVICE: FUEL 100LL LGT Dusk-dawn. ACTIVATE LIRL Rwy 16-34- AIRPORT REMARKS: Attended Mon-Thu 1330-2330Z‡, Fri 1330-2300Z‡ TPA—Fixed wing acft 1690 (800). AIRPORT MANAGER: 785-594-2741 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8 	. Fuel only avbl opr hrs or with prior arrangement
 BEAUMONT HOTEL (Ø7S) 0 E UTC-6(-5DT) N37°39.56' W96 1617 NOTAM FILE ICT RWY 18-36: 2400X80 (TURF) 1.1% up N RWY 18: Road. RWY 36: Tree. Rgt ffc. AIRPORT REMARKS: Unattended. Rwy ends line of site obstructed by terrain turbine farm and 420' twr 3 miles south southwest. 4' barbwire fend WSW of arpt. Occasional large round hay bales both sides of rwy. 20 hotel/restaurant. Rwy 18-36 marked with yellow cones. AIRPORT MANAGER: 620-843-2422 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8 	n. After hours or emerg call 316–377–3085. Win te 260´ from apch end Rwy 18. 365 ft twr 0.7 Nf ´ x 1200´ paved twy to acft parking at
BEECH FACTORY (See WICHITA on page 143) BELLEVILLE MUNI (RPB)(KRPB) 1 W UTC-6(-5DT) N39°49.0 1538 B NOTAM FILE ICT RWY18-36: H3500X60 (ASPH) S-12.5, D-18 MIRL 0.4% up S RWY18: PAPI(P2L)—GA 3.0° TCH 41 ⁻⁷ , Railroad. Railroad. Second 2000 Second 2000)7´ W97°39.58´ Wichi L-1 I