

ERROL (ERR)(KERR) 1 NW UTC-5(-4DT) N44°47.53' W71°09.87' **MONTREAL**
 1248 TPA—2048(800) NOTAM FILE BGR
RWY 15-33: 3600X60 (GRVL) 0.3% up SE
RWY 15: Trees.
AIRPORT REMARKS: Unattended. For arpt information and conditions, call 603-482-3320. Wildlife on and in/ov arpt. Regular construction vehicle t/c on roadway at Rwy 33 end. 1:1 clearance slope. Rwy 15-33: Rwy soft in spring. Lrg patches of grass on rwy.
AIRPORT MANAGER: 603-616-8602
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.
 •
HELIPAD H1: H61X61 (ASPH)
HELIPAD H1: Trees.
HELIPORT REMARKS: ACTIVATE helipad flood lgt and lighted windcone—CTAF.

FITZY N42°51.85' W71°31.73' NOTAM FILE MHT. **NEW YORK**
NDB (LOMW) 209 MJ 060° 5.8 NM to Manchester Boston Rgnl. 234/15W.

FRANCONIA (1B5) 2 S UTC-5(-4DT) N44°11.76' W71°45.04' **MONTREAL**
 975 NOTAM FILE BGR
RWY 18-36: 2300X150 (TURF) 0.9% up S
RWY 18: Trees.
RWY 36: Pole. Rgt t/c.
NOISE: Tkofs and l/ds not adzd fm dusk to 1400Z† for voluntary noise abatement.
AIRPORT REMARKS: Attended May-Oct Sat-Sun 1500-2300Z†. Also atndd on wkday hols. Ctc amgr for non-hol wkday atndnc. Wildlife on and in/ov arpt. Glider opr in/ov arpt. For arpt conditions call 603-823-5034. Rwy soft in spring. First 200 ft of Rwy 18 rough. Avoid flying over residential area at departure end Rwy 18 during both takeoff and landing; avoid low alt and/or high power settings in this area. 4' tall fence 92' fm Rwy 36 L to R of cntrln. Rwy 36 Rgt t/c: L pat for gldrs. In case of emergency ctc New Hampshire State Police 800-525-5555.
AIRPORT MANAGER: 603-921-1588
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

GIFFORD FLD (See COLEBROOK on page 150)

GORHAM (2G8) 1 NW UTC-5(-4DT) N44°23.61' W71°11.89' **MONTREAL**
 835 NOTAM FILE BGR
RWY 12-30: 2828X60 (TURF) 1.2% up SE
RWY 12: Thld dspcd 250'. Trees.
RWY 30: Thld dspcd 250'. Trees.
AIRPORT REMARKS: Unattended. Arpt CLOSED Nov 1-May 15. Otr times ck NOTAMS or durg nml bus hrs only call 603-466-3302, lve fone nr and exp rtm call for FICON. Wildlife on and in/ov arpt. Rflg and maint of acft is prohibited. Arpt oprd and maint by Town of Gorham Water and Sewer Dept. AER 30 soft in spring/heavy rains. Rwy sfc rolling and uneven. Rwy 12-30 edges and ends mkd by yellow cones. Camping prohibited on arpt.
AIRPORT MANAGER: 603-466-5065
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

HAMPTON AIRFIELD (7B3) 2 N UTC-5(-4DT) N42°57.68' W70°49.81' **NEW YORK**
 93 NOTAM FILE BGR
RWY 02-20: H2105X121 (ASPH-TURF) LIRL(NSTD) 0.3% up N
RWY 02: Trees.
RWY 20: Thld dspcd 212'. Trees.
SERVICE: S3 FUEL 100LL, MOGAS LGT RWY 02-20 NSTD LIRL. CTC AMGR at 603-817-6617 for activation instructions.
AIRPORT REMARKS: Attended 1300-2100Z†, exc Thanksgiving and Christmas. Wildlife on and in/ov arpt. Self-svc 100LL and MOGAS avbl 24 hrs via credit card. Caution: short and soft fld ops. For short fld trng or info pls ctc amgr 603-817-6617. Extensive student pilot and training ops at arpt. Parallel rwy ops not permitted. Pilot will designate and make radio call to adz turf or grass ldg/tkof. Numerous NORDO acft opr at arpt. Road at Rwy 20 thld with moderate vehicle t/c. Rwy 02-20 2105 ft X 46 ft asph on W portion, 2105 ft X 75 ft on E portion. Rwy 20 NSTD dthr; sngl red/green lgt each side. Thr siting sfc 10:1 slp.
AIRPORT MANAGER: 603-964-6749
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Boston Apch at 603-594-5552.