

BINGHAMTON**GREATER BINGHAMTON/EDWIN A LINK FLD** (BGM)(KBGM) 7 N UTC-5(-4DT)

NEW YORK

N42°12.51' W75°58.78'

H-10H, 11C, 12J, L-30J, 32F, 33A

1636 B TPA-2436(800) Class I, ARFF Index B NOTAM FILE BGM MON Airport

IAP, AD

RWY 16-34: H7305X150 (ASPH-GRVD) S-112, D-147, 2S-159, 2D-221 PCN 45 F/D/X/T

HIRL 0.9% up NW

RWY 16: MALSR. PAPI(P2L)—GA 3.0° TCH 61'. RVR-TR Thld dsplcd 400'. Antenna.**RWY 34:** MALSR. PAPI(P2L)—GA 3.0° TCH 64'. RVR-TR Thld dsplcd 205'.**RWY 10-28:** H5001X150 (ASPH-GRVD) S-81, D-103, 2S-159, 2D-168 PCN 32 F/D/X/T MIRL 0.4% up W**RWY 10:** VASI(V4L)—GA 3.0° TCH 53'.**RWY 28:** REIL. VASI(V4L)—GA 3.0° TCH 45'.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 10:** TORA-5001 TODA-5001 ASDA-5001 LDA-5001**RWY 16:** TORA-7305 TODA-7305 ASDA-7305 LDA-6905**RWY 28:** TORA-5001 TODA-5001 ASDA-5001 LDA-5001**RWY 34:** TORA-7305 TODA-7305 ASDA-7305 LDA-7100**ARRESTING GEAR/SYSTEM****RWY 16:** EMAS**RWY 34:** EMAS**SERVICE:** S2 FUEL 100LL, JET A 0X3, 4 LGT When twr clsd ACTIVATE MALSR Rwy 16 and Rwy 34, HIRL Rwy 16-34, MIRL Rwy 10-28 and twy lgts—CTAF.**AIRPORT REMARKS:** Attended continuously. Lgtd structure 118' AGL 2000' south of AER 10. Bird activity on and invof arpt.

Rwy 10 tkofs and ldgs na when twr clsd. PPR 12 hrs for unscheduled air carrier ops with more than 9 passenger seats 0400-1100Z± call arpt manager 607-763-4474. ARFF avbl 1030-0500Z± and/or until 15 min after the last scheduled air carrier opr. Twr unable to see hard sfc south of FBO hangar. FBO svcs avbl 0930-0300Z± Sun to Sat. For aft hrs FBO svcs ctc 607-643-1640. Ldg fee for multi-engine and turbine acft over 4000 lbs. User fee arpt.

AIRPORT MANAGER: 607-763-4471**WEATHER DATA SOURCES:** ASOS (607) 729-8335**COMMUNICATIONS:** CTAF 119.3 ATIS 128.15 UNICOM 122.95

BINGHAMTON RCO 122.1R 112.2T (BUFFALO RADIO)

Ⓡ BINGHAMTON APP/DEP CON 118.6 (Sfc-5000') 127.55 (6000-8000') (1100-0500Z±)

Ⓡ NEW YORK CENTER APP/DEP CON 132.175 (0500-1100Z±)

BINGHAMTON TOWER 119.3 (1100-0500Z±) GND CON 121.9 CLNC DEL 125.05

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc New York ARTCC at 631-468-1425.**AIRSPACE:** CLASS D svc 1100-0500Z±; other times CLASS E.**TRSA** svc ctc APP CON**RADIO AIDS TO NAVIGATION:** NOTAM FILE BUF.

BINGHAMTON (L) (L) VOR/DME 112.2 CFB Chan 59 N42°09.45' W76°08.19' 076° 7.6 NM to fld. 1583/10W.

VOR unusable:

023°-033° byd 15 NM blo 6,000'

ILS 110.3 I-AAJ Rwy 16. Class IB. Unmonitored when twr clsd.

ILS 110.3 I-BGM Rwy 34. Class IA. Unmonitored when twr clsd.

COMM/NAV/WEATHER REMARKS: For Clnc Del when twr clsd ctc Buffalo Radio on CFB RCO 122.1R 112.2T.

HELIPAD HI: H54X54 (ASPH) PERIMETER LGTS

HELIPORT REMARKS: Helipad located at the intersection of Twy L and the west apron.

BLUE HERON (See GALLUPVILLE on page 208)