

EAST HAMPTON TOWN (JPX)(KJPX) PVT 3 W UTC-5(-4DT) N40°57.57' W72°15.10' **NEW YORK**
AIRSPACE: CLASS D svc 1300-0100Z±, oprs Sat bfr memorial day to Sun aft labor day; other times CLASS E. **L-33C, L-341**
IAP

EAST MORICHES

LUFKER (49N) 1 NE UTC-5(-4DT) N40°49.49' W72°45.06' **NEW YORK**
 57 NOTAM FILE ISP **COPTER**
RWY N-S: 2300X100 (TURF)
RWY N: Trees.
RWY S: Tree. Rgt tfc.
AIRPORT REMARKS: Attended dalgt hrs. Banner towing ops May-Oct. Glider and ultralights ops dalgt hrs May-Oct. Seatuck arpt tfc pat 590' east. Rwy N acft tiedowns 25-30' rgt from centerline 100-450' southend of rwy. Rwy N +35' powerlines 80' from rwy beginning, road 45' from rwy beginning. Rwy N has acft tiedown 40' from thd right. Rwy N-S south end of rwy marked with boards. Ldg fee.
AIRPORT MANAGER: 516-203-5930
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2449.

SEATUCK (1N2) 1 NE UTC-5(-4DT) N40°49.67' W72°44.92' **NEW YORK**
 50 NOTAM FILE ISP **COPTER**
RWY 18-36: H2400X25 (ASPH) S-12.5
RWY 18: Trees.
RWY 36: Thld dsplcd 485'. P-line. Rgt tfc.
NOISE: Use north opn for tkf with no wind; heavy gross weight; and for noise abatement.
AIRPORT REMARKS: Attended May-Oct dalgt hrs. Arpt CLOSED indef. Parachute Jumping. Ultralghts on and infov arpt. PAEW 75' east of Rwy 18. Due to close proximity of Lufker arpt (590' between rwys) adhere to the following tfc pat. North ops, Seatuck-Rgt tfc, Lufker-Left tfc. South ops, Seatuck-Left tfc, Lufker-Rgt tfc. Arrivals, intercept final apch 45° to final apch leg 1500' from apch end of rwy. Departures, make 45° turn as soon as possible after tkf to intercept crosswind leg. Use south ops for ldg when winds are 5 kts or less, or when winds are more than 5 kts 90° either side of centerline. Rwy 18-36 vegetation in cracks.
AIRPORT MANAGER: 646-363-6297
COMMUNICATIONS: CTAF/UNICOM 123.0
CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2449.

EDINBURG

PLATEAU SKY RANCH (1F2) 1 NW UTC-5(-4DT) N43°13.53' W74°06.87' **NEW YORK**
 1070 NOTAM FILE BTW
RWY 06-24: 2400X100 (TURF) 0.5% up NE
RWY 06: Road.
RWY 24: Road.
RWY 01-19: 2000X100 (TURF) 1.0% up N
RWY 01: Trees.
RWY 19: Trees.
AIRPORT REMARKS: Unattended. Ultralgt acft on and infov arpt. Rwy 1; +30'-60' trees, 0'-240' from thld, 15'-100' left and right of centerline. Rwy 6; +20'-65' trees, 0'-500' from thld, 30'-150' left and right of centerline. Rwy 19; +17'-52' trees, 0'-230' from thld, 50'-100' right of centerline. Rwy 24; +35'-50' trees, 90'-250' from thld, 0'-125' right of centerline and +50' trees, 350'-425' from thld 110'-150' left of centerline. Rwy 01-19 edges marked with red cones all seasons exc winter. Rwy 06-24 edges marked with red cones all seasons exc winter. Arpt not plowed or mntnd durg winter months, rwy sfc can be soft as frost leaves the grd in spring. Acft parked/hangared on non-arpt land. Cross public road to/from arpt.
AIRPORT MANAGER: 518-863-2725
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Albany Apch at 518-862-2299.