

MILLBROOK

SKY ACRES (44N) 6 SW UTC-5(-4DT) N41°42.45' W73°44.28'

NEW YORK

697 NOTAM FILE ISP

L-33B, 34I

RWY 17-35: H3828X60 (ASPH) S-20 MIRL 1.3% up S

IAP

RWY 17: Trees.

RWY 35: PAPI(P2L)—GA 3.0° TCH 33'. Trees.

SERVICE: S4 FUEL 100LL LGT ACTIVATE PAPI Rwy 35; MIRL Rwy 17-35—CTAF. PAPI Rwy 35 unusbl 8° right of cntrln.

AIRPORT REMARKS: Attended 1300-2100Z†. Self-svc fuel avbl 24 hrs. Rwy 17-35 safety areas have 30' dropoffs sloping 20' from thld at both ends. Parallel twy not lgtd. Cold temperature airport. Altitude correction required at or below -23C.

AIRPORT MANAGER: 845-677-5010

COMMUNICATIONS: CTAF/UNICOM 122.8

® **NEW YORK APP/DEP CON** 132.75

CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2448

RADIO AIDS TO NAVIGATION: NOTAM FILE ISP.

KINGSTON (VL) (L) VOR/DME 117.6 IGN Chan 123 N41°39.93' W73°49.33' 068° 4.5 NM to fld. 581/12W.

VOR unusable:

008°-018° byd 40 NM blo 4,000'

008°-018° byd 70 NM

020°-123° byd 40 NM

045°-050° byd 35 NM blo 4,300'

070°-140° byd 30 NM blo 3,400'

082°-092° byd 20 NM blo 4,000'

082°-092° byd 35 NM blo 5,500'

130°-148° byd 40 NM

203°-216° byd 30NM


243°-253° byd 40 NM

275°-310° byd 40 NM

311°-321° byd 40 NM blo 6,000'

311°-321° byd 64 NM

322°-001° byd 40 NM



MISSE N44°51.25' W74°54.95' NOTAM FILE MSS.

NDB (LOMW) 278 MS 045° 5.8 NM to Massena Intl-Richards Fld. 245/14W.