

POINT PLEASANT**MASON CO** (312) 4 NE UTC-5(-4DT) N38°54.88' W82°05.91'

643 B NOTAM FILE EKN


RWY 07-25: H4000X75 (ASPH) S-24 MIRL 0.3% up SW**RWY 07:** REIL. PAPI(P2L)—GA 3.0° TCH 44'. Trees.**RWY 25:** REIL. PAPI(P2L)—GA 3.0° TCH 43'. Trees.**SERVICE:** **FUEL** 100LL **LGT** Actvt REIL Rwy 07 and 25; PAPI Rwy 07 and 25; MIRL Rwy 07-25—CTAF.

AIRPORT REMARKS: Attended 1500-1900Z Mon-Fri. Deer on and in vicinity of arpt. Steam from cooling twrs NW occasionally obscures obstruction lgts on twr North. 100LL self svc. Rwy 07 has 3' ditch 80' L and R of cntrln first 1000'. 6-8' brush parallel to Rwy 25, 95' fm centerline. Portion of ramp and one rwy exit unsafe due to soft weak asph paving. Area marked by lgtd barricade unusable. Cold temperature airport. Altitude correction required at or below -17C. Several power plant stacks in vicinity of arpt west and north. Rwy 25, 35' drop off, 100' fm rwy end.

AIRPORT MANAGER: 304-674-5075**WEATHER DATA SOURCES:** AWOS-3 119.675 (304) 675-4618.**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **HUNTINGTON APP/DEP CON** 128.4**CLEARANCE DELIVERY PHONE:** For CD ctc huntington ATCT at 304-453-2490.**RADIO AIDS TO NAVIGATION:** NOTAM FILE EKN.**HENDERSON (H) DME** 115.9 HNN Chan 106 N38°45.25' W82°01.57' 341° 10.2 NM to fld. 880.

DME unusable:

185°-290° blo 4,500'



CINCINNATI

L-29B

IAP

POTOMAC AIRPARK (See BERKELEY SPRINGS on page 400)**RALEIGH CO MEML** (See BECKLEY on page 399)**RANDOLPH CO** N38°53.64' W79°51.56' NOTAM FILE EKN.**NDB (HW) 284** RQY at Elkins/Randolph Co (Jennings Randolph Fld). 1938/7W.

NDB unusable:

018°-084° byd 10 NM

085°-017° byd 15 NM

CINCINNATI

L-29C