

**SARATOGA**

**SHIVELY FLD** (SAA)(KSAA) 1 SW UTC-7(-6DT) N41°26.61' W106°49.65'

7014 B NOTAM FILE CPR

**RWY 05-23:** H8801X100 (ASPH-GRVD) S-50 PCN 50 F/D/X/U MIRL

**RWY 05:** REIL. PAPI(P4L)—GA 3.0° TCH 49'. 1.8% down.

**RWY 23:** REIL. PAPI(P4L)—GA 3.0° TCH 47'. 1.8% up.

**SERVICE:** FUEL 100LL, JET A LGT ACTVT REIL Rwy 05 and Rwy 23; PAPI Rwy 05 and Rwy 23; MIRL Rwy 05-23—CTAF.

**AIRPORT REMARKS:** Attended 1500-0000Z. Full svc fuel. Aft hrs call 307-326-8344. Antelope may be on rwy. Wind shear over highway approach end of Rwy 23. Lndg fee: turbine & jet acct only. Fees vary based on cat of acct.

**AIRPORT MANAGER:** 307-326-8344

**WEATHER DATA SOURCES:** AWOS-3PT 118.175 (307) 326-5387.

**COMMUNICATIONS:** CTAF/UNICOM 122.8

Ⓡ **DENVER CENTER APP/DEP CON** 132.1

**CLEARANCE DELIVERY PHONE:** For CD ctc Denver ARTCC at 303-651-4257.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE CPR.

**CHEROKEE (VH) (H) VORW/DME** 115.0 CKW Chan 97 N41°45.34' W107°34.92' 104° 38.8 NM to fld. 7050/15E.

VOR unusable:

000°-015° byd 40 NM

082°-085° byd 40 NM


114°-116° byd 40 NM

125°-135° byd 40 NM

**CHEYENNE**

H-3E, L-9E, 11E

IAP



**SHERIDAN CO**

(SHR)(KSHR) 2 SW UTC-7(-6DT) N44°46.15' W106°58.82'

4021 B TPA—See Remarks Class I, ARFF Index A NOTAM FILE SHR MON Airport

**RWY 15-33:** H8301X100 (ASPH-PFC) S-60, D-75, 2S-95

PCN 22 F/B/X/U HIRL

**RWY 15:** REIL. PAPI(P4L)—GA 3.0° TCH 50'. 0.5% down.

**RWY 33:** MALSR. PAPI(P4L)—GA 3.0° TCH 54'. 0.4% up.

**RWY 06-24:** H5039X75 (ASPH-GRVD) S-36, D-50 PCN 11 F/B/X/U

MIRL 1.6% up SW

**RWY 06:** REIL. PAPI(P4L)—GA 4.0° TCH 57'.

**RWY 24:** REIL. PAPI(P4L)—GA 3.0° TCH 39'. Trees.

**RUNWAY DECLARED DISTANCE INFORMATION**

**RWY 06:** TORA-5039 TODA-5039 ASDA-5039 LDA-5039

**RWY 15:** TORA-8301 TODA-8301 ASDA-8301 LDA-8301

**RWY 24:** TORA-5039 TODA-5039 ASDA-5039 LDA-5039

**RWY 33:** TORA-8301 TODA-8301 ASDA-8301 LDA-8301

**SERVICE:** S4 FUEL 100, JET A, A1+ OX 1, 2, 3 LGT ACTVT MALSR Rwy 33; REIL Rwy 06, 24, and 15; PAPI Rwy 06, 24, 15, and 33; HIRL Rwy 15-33; MIRL Rwy 06-24—CTAF.

**AIRPORT REMARKS:** Attended dalgt hrs. Conds not monitored at ngt aft the last acr arr til 0500L. See NOTAMS for the most up-to-date conds and updts. Cold temperature airport. Altitude correction required at or below -19C. PPR unscheduled acct ops with more than 30 passenger seats ctc ARFF station 307-673-1875. Fixed wing acct rstd to rwys and twys only. TPA-4821(800) for single engine, and 5521(1500) for turboprop and jet.

**AIRPORT MANAGER:** 307-674-4222

**WEATHER DATA SOURCES:** ASOS 135.175 (307) 672-5349. SAWRS 1100-0600Z.

**COMMUNICATIONS:** CTAF/UNICOM 123.0

RCO 122.5 (CASPER RADIO)

Ⓡ **SALT LAKE CENTER APP/DEP CON** 127.75

**CLEARANCE DELIVERY PHONE:** For CD if una to ctc on FSS freq, ctc Salt Lake ARTCC at 801-320-2568.

**AIRSPACE:** CLASS E.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE SHR.

(VL) (DH) **VORW/DME** 113.55 SHR Chan 82(Y) N44°50.54' W107°03.67' 132° 5.6 NM to fld. 4397/10E.

VOR unusable:

146°-162° byd 40 NM

163°-270° byd 12 NM

271°-280° byd 40 NM

DME unusable:

163°-270° byd 12 NM

**ILS/DME** 108.7 I-SHR Chan 24 Rwy 33.

**BILLINGS**

H-1E, 2G, L-13D

IAP, AD

