MOLOKAI
 (MKK)(PHMK)
 6 NW
 UTC-10
 N21°09.17′ W157°05.78′

 454
 B
 TPA—See Remarks
 Class I, ARFF Index A
 NOTAM FILE MKK

 RWY 05-23: H4494X100 (ASPH-GRVD)
 S-30, D-48
 PCN 28 F/A/W/T
 MIRL

HAWAIIAN ISLANDS P-2G IAP, AD

0.4% up NE

RWY 05: REIL. PAPI(P4L)-GA 4.0° TCH 497

RWY 23: Thid dsplcd 593'. Brush.

RWY 17-35: H3118X100 (ASPH) S-13 PCN 04 F/B/W/T MIRL

0.6% up N

RWY 17: Thid dsplcd 426'. Fence.

RWY 35: Fence.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 05: TORA-4494 TODA-4494 ASDA-4494 LDA-4494 **RWY 17**: TORA-3118 TODA-3118 ASDA-3118 LDA-2692 **RWY 23**: TORA-4494 TODA-4494 ASDA-4494 LDA-3901

RWY 35: TORA-3118 TODA-3118 ASDA-3118 LDA-3118

SERVICE: LGT When twr closed ACTIVATE MIRL Rwy 05–23 and Rwy 17–35, REIL Rwy 05—CTAF. Rwy 05 PAPI not authorized 1.8 NM byd landing thId due to rapidly rising terrain.

AIRPORT REMARKS: Attended 1500–0615Z. Be alert to egrets and pigeons on and in vicinity of arpt. TPA—small acft 1250(796) large acft 1950(1496). Arpt CLOSED to air carrier operations with more than 10 passenger seats 0530–1600Z except PPR call (808)

Standing water/ponding on Rwy 17-35 near Twy Echo during inclement weather.



AIRPORT MANAGER: (808) 872-3808

WEATHER DATA SOURCES: ASOS (808) 567-6106

COMMUNICATIONS: CTAF 125.7 ATIS 128.2

MOLOKAI RCO 122.1R 116.1T (HONOLULU RADIO)

RHCF CENTER APP/DEP CON 124.1

TOWER 125.7 (1600-0430Z) GND CON 121.9

CLEARANCE DELIVERY PHONE: For CD when ATCT is clsd ctc Honolulu Control Facility at 808-840-6262.

AIRSPACE: CLASS D svc 1600-0430Z other times CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE MKK.

(H) VORTAC 116.1 MKK Chan 108 N21°08.29′ W157°10.05′ 067° 4.1 NM to fld. 1421/11E.

VORTAC unusable:

275°-285° byd 25 NM blo 3,500°

