
DYESS AAF (ROI)(PKRO) UTC+12 N09°23.81' E167°28.25' P-1B
 14 B
RWY 04-22: H4499X150 (ASPH) PCN 11 F/B/W/T
RWY 04: PAPI(P4L)—GA 3.0° TCH 38'.
RWY 22: PAPI(P4L)—GA 3.0° TCH 38'.
AIRPORT REMARKS: No facilities—ARFF available. No transient acft authorized. Electromagnetic radiation will exist 24 hrs daily within 10 NM radius of Dyess AAF from surface to 50,000. Acft within the abv airspace will be exposed to direct radiation which may produce harmful effect to persons and equipment. REIL available Rwy 04 with prior notice. Five lighted antennae; 263 dish located 0.6 NM E, 175 dish located 0.7 NM ENE, 273 located 1.3 NM SE. 150 located 800S, 210 located 0.4 NM NNW. Military rotating beacon atop 137 water tower 950 SE. Taxiway lighted. NOTE: See Area Notices—MARSHALL ISLANDS.
COMMUNICATIONS:
SAN FRANCISCO ARINC (HNL) NOTAM FILE HNL.
ROI RADIO 118.1

MAJURO ATOLL

MAJURO N07°03.92' E171°16.11' NOTAM FILE HNL P-1B
NDB/DME (HW/DME) 316 MAJ Chan 114 at Marshall Islands Intl. 4/10E. DME Chan 114 paired with VHF freq 116.7

AMATA KABUA INTL (MAJ)(PKMJ) 7 SW UTC+12 N07°03.90' E171°16.32' P-1B
 7 B NOTAM FILE HNL IAP
RWY 07-25: H7913X150 (ASPH-GRVD) S-120, D-171, 2D-290 PCN 64 F/B/X/T MIRL
RWY 07: REIL. PAPI(P4L)—GA 3.0° TCH 55'.
RWY 25: REIL. PAPI(P4L)—GA 3.0° TCH 46'. Tree.
SERVICE: FUEL JET A1+ **LGT** ACTIVATE MIRL Rwy 07-25, PAPI and REIL Rws 07 and 25—CTAF.
AIRPORT REMARKS: Attended on request. PPR for ldg from arpt mgr 24 hrs in advance. After sender has confirmed fuel delivery, he must give 24 hours advance notice to Airport Superintendent and Immigration Officer, Majuro, Marshall Islands. If ETA is between 0400Z Fri to 2200Z Mon, 48 hours advance notice must be given to Airport Superintendent. Message will include name of sender, type of aircraft, aircraft identification number, ETA purpose of landing, such as ferry flight, number of crew, PAX and citizenships, and that sender has obtained fuel confirmation from MOBILE OIL Guam including quantity and type of fuel. Include RON in message if applicable. Arpt Superintendent available Sun-Fri 2000-0500Z phone (692) 247-7612/3113, Fax (692) 247-3888.
AIRPORT MANAGER: (692) 247-3113
COMMUNICATIONS: CTAF 123.6
MAJURO RADIO 123.6 LAA 126.6 emerg only 5205X USB emerg only 2182 emerg only.
RADIO AIDS TO NAVIGATION:
MAJURO NDB/DME (HW/DME) 316 MAJ Chan 114 N07°03.92' E171°16.11' at fld. 4/10E. DME Channel 114 paired with VHF freq 116.7.

MEJIT ATOLL

MEJIT (C3Ø) 0 NE UTC+12 N10°17.00' E170°53.00'
 5 NOTAM FILE HNL Not insp.
RWY 07-25: 3000X50 (GRVL-CORAL)
AIRPORT REMARKS: Attended on call.
AIRPORT MANAGER: (692) 625-6179
COMMUNICATIONS: CTAF 122.9
