

## DRYDEN

**TERRELL CO** (6R6) 5 W UTC-6(-5DT) N30°02.79' W102°12.79'

SAN ANTONIO

2323 B NOTAM FILE SJT

L-19A

**RWY 13-31:** H4526X75 (ASPH) S-30 MIRL 0.7% up NW

**RWY 13:** Fence.

**RWY 04-22:** H4525X75 (ASPH) S-30 0.3% up SW

**RWY 22:** Brush.

**SERVICE:** LGT Actvt MIRL Rwy 13-31—CTAF. Heli pad lgts, 5 clicks—123.05.

**AIRPORT REMARKS:** Attended intmnt. Rwy 04-22 and Rwy 13-31 extensive cracking, loose stones on sfc. Rwy 13-31 and Rwy 04-22 marking poor due to pavement deterioration.

**AIRPORT MANAGER:** 432-345-6731

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Houston ARTCC at 281-230-5622.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE FST.

**FORT STOCKTON (VH) (H) VORTACW** 116.9 FST Chan 116 N30°57.13' W102°58.54' 133° 67.1 NM to fld. 2893/11E.

VOR unusable:

020°-055° byd 20 NM blo 6,900'

070°-086° byd 35 NM blo 6,400'

106°-132° byd 30 NM blo 5,900'

125°-202° byd 40 NM

203°-213° byd 40 NM blo 18,000'

214°-230° byd 40 NM

245°-255° byd 40 NM

315°-330° byd 30 NM blo 5,400'

**DUBLIN MUNI** (9F0) 2 SE UTC-6(-5DT) N32°04.09' W98°19.52'

DALLAS-FT WORTH

1495 B NOTAM FILE FTW

L-17B

**RWY 15-33:** H3200X60 (ASPH) S-12.5 MIRL

**RWY 15:** P-line.

**SERVICE:** FUEL , UL94 LGT ACTIVATE MIRL Rwy 15-33 —123.5.

**AIRPORT REMARKS:** Attended Wed-Fri 1500-0300Z‡, Sat 1500-2000Z‡.

Deer and wildlife on and in/ov arpt.

**AIRPORT MANAGER:** (254) 434-1082

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Fort Worth ARTCC at 817-858-7584.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE FTW.

**GLEN ROSE (L) TACAN** Chan 97 JEN (115.0) N32°09.58'

W97°52.66' 251° 23.5 NM to fld. 1300/6E.

