

ORLAND

HAIGH FLD (O37) 3 SE UTC-8(-7DT) N39°43.22' W122°08.78'

SAN FRANCISCO

218 B NOTAM FILE RIU

L-2G

RWY 15-33: H4500X60 (ASPH) S-30 MIRL

IAP

RWY 15: PAPI(P2L)—GA 3.5° TCH 28'. Road.

RWY 33: PAPI(P2L)—GA 3.5° TCH 27'. Pole.

SERVICE: S4 FUEL 100LL LGT ACTVT MIRL Rwy 15-33—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1500-2330Z†. Ultralight activity on and in/ov arpt.

AIRPORT MANAGER: 530-934-6530

COMMUNICATIONS: CTAF/UNICOM 122.7

Ⓡ **OAKLAND CENTER APP/DEP CON** 132.2

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.

RADIO AIDS TO NAVIGATION: NOTAM FILE RBL.

RED BLUFF (VH) (H) VORTACW 115.7 RBL Chan 104 N40°05.93' W122°14.18' 152° 23.1 NM to fld. 321/18E.

VOR unusable:

015°-087° byd 40 NM

174°-178° byd 40 NM

188°-267° byd 40 NM


268°-278° byd 40 NM blo 8,000'

268°-278° byd 63 NM

279°-287° byd 40 NM

280°-300° blo 3,500'

298°-304° byd 40 NM



OROVILLE

LAKE OROVILLE LANDING AREA SPB (O06) 5 NE UTC-8(-7DT) N39°33.99' W121°28.06'

SAN FRANCISCO

900 TPA—1700(800) NOTAM FILE RIU

WATERWAY ALL-WAY: 9000X9000 (WATER)

SERVICE: FUEL MOGAS

SEAPLANE REMARKS: Unattended. For lake information ctc marina 530-589-3152. Lake elevation varies from 700'-900'

MSL. Waterway all way ldg area located in center of main body of lake. Waterway all way ldg zone is a 9,000 ft diameter circular area in center of main body of lake.

AIRPORT MANAGER: (916) 532-3085

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.

OROVILLE MUNI (OVE)(KOVE) 3 SW UTC-8(-7DT) N39°29.27' W121°37.32'

SAN FRANCISCO

194 B TPA—994(800) NOTAM FILE OVE

H-3B, L-2G

RWY 02-20: H6020X100 (ASPH) S-47, D-90 HIRL

IAP

RWY 02: REIL. PAPI(P2L)—GA 3.0° TCH 44'.

RWY 20: REIL. PAPI(P2L)—GA 3.0° TCH 40'.

RWY 13-31: H3540X100 (ASPH) S-19, D-31 HIRL 0.4% up NW

RWY 13: PAPI(P2L)—GA 3.0° TCH 39'.

RWY 31: PAPI(P2L)—GA 3.0° TCH 29'. Trees.

SERVICE: S3 FUEL 100LL, JET A LGT ACTVT REIL Rwy 02 and 20;

PAPI Rwy 02, 13, 20 and 31; HIRL Rwy 02-20 and Rwy

13-31—CTAF. VGSI Rwy 20 does not provide obstruction clearance byd 3 NM.

AIRPORT REMARKS: Attended Mon-Sat 1600-0100Z†. For Arpt information Mon-Fri ctc (530) 538-2490. Firefighting acct in/ov arpt May-Oct. Twy from Rwy 02-20 to golf course/restaurant tiedowns 20' wide with no shoulders.

AIRPORT MANAGER: 530-538-2490

WEATHER DATA SOURCES: ASOS 121.425 (530) 533-5792.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ **NORCAL APP/DEP CON** 125.4

CLEARANCE DELIVERY PHONE: For CD ctc NorCal Apch at 916-361-6874.

RADIO AIDS TO NAVIGATION: NOTAM FILE MYV.

MARYSVILLE (T) (T) VOR/DME 110.8 MYV Chan 45 N39°05.92' W121°34.38' 338° 23.4 NM to fld. 62/16E.

VOR unusable:

275°-295° byd 28 NM blo 6,000'

DME unusable:

275°-295° byd 28 NM blo 6,000'

