

CONTINUED FROM PRECEDING PAGE

RADIO AIDS TO NAVIGATION: NOTAM FILE DRO.

(VL) (DH) VORW/DME 116.55 DRO Chan 112(Y) N37°09.20' W107°44.98' at fld. 6662/14E.

VOR unusable:

- 004°-014° byd 40 NM blo 16,500'
- 004°-014° byd 50 NM
- 015°-070° byd 40 NM
- 131°-190° byd 40 NM
- 220°-225° byd 40 NM
- 250°-003° byd 40 NM
- 290°-310° byd 15 NM blo 17,000'

DME unusable:

- 070°-090° byd 30 NM blo 12,500'
- 140°-185° byd 25 NM blo 13,000'
- 290°-310° byd 15 NM blo 17,000'

ILS 109.1 I-DRO Rwy 03. Class IE.

EADS MUNI (9V7) 1 W UTC-7(-6DT) N38°28.51' W102°48.65'

WICHITA
L-10G

4245 NOTAM FILE DEN

RWY 17-35: H3860X60 (ASPH) MIRL

RWY 17: Road.

RWY 35: Road.

AIRPORT REMARKS: Unattended. Be alert, intensive USAF student training invof Colorado Springs and Pueblo Colorado. Rwy 17 +25' bldgs 300' right of centerline 108' from rwy end. Rwy 17 has +25' railroad 530' from thld centerline. Apron area is asph. Twy and rwy have no markings. See Special Notices—USAF 306 FTG Flight Training Areas, Vicinity of Colorado Springs and Pueblo Colorado.

AIRPORT MANAGER: 719-438-5590

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Denver ARTCC at 303-651-4257.

RADIO AIDS TO NAVIGATION: NOTAM FILE LAA.

LAMAR (VH) (DH) VORW/DME 116.9 LAA Chan 116 N38°11.83' W102°41.25' 329° 17.7 NM to fld. 3944/12E.

