

FLINT, MICHIGAN

AL-618 (FAA)

21112

| | | |
|---|------------------------|---|
| VORTAC FNT 116.9 Chan 116 | APP CRS 359° | Rwy Idg 7648 TDZE 782 Apt Elev 782 |
|---|------------------------|---|



VOR RWY 36

BISHOP INTL (FNT)

⚠ Rwy 36 helicopter visibility reduction below 3/4 SM NA. DME required.

⚠ MISSED APPROACH: Climbing right turn to 3000 on FNT VORTAC R-097 to KATTY/10.3 DME and hold.

| | | | | | |
|-----------------------|---|--|-------------------------|---------------------------|-------------------------|
| ATIS 133.15 | GREAT LAKES APP CON * 118.8 257.9 | FLINT TOWER * 126.3 (CTAF) 0 257.9 | GND CON 121.9 | CLNC DEL 121.75 | UNICOM 122.95 |
|-----------------------|---|--|-------------------------|---------------------------|-------------------------|



| | | | | |
|-------------------|-----------------------|-----------------------|-------------------------------|-------------------------------|
| CATEGORY | A | B | C | D |
| S-36 | 1220-1 | 438 (500-1) | 1220-1 1/4 | 438 (500-1 1/4) |
| C CIRCLING | 1240-1 458 (500-1) | 1300-1 518 (600-1) | 1300-1 1/2 518 (600-1 1/2) | 1520-2 1/4 738 (800-2 1/4) |

FLINT, MICHIGAN
Orig-A 24MAY18

42°58'N-83°45'W

BISHOP INTL (FNT) VOR RWY 36

EC-1, 09 SEP 2021 to 07 OCT 2021

EC-1, 09 SEP 2021 to 07 OCT 2021