


LOC RWY 34
SOUTH ST PAUL MUNI/RICHARD E FLEMING FLD (SGS)

MISSED APPROACH: Climbing right turn to 3000 on heading 100° and on GEP VORTAC R-125 to PRESS INT/21.7 DME and hold.

UNICOM
122.7 (CTAF) 

FAF to MAP 5.1 NM

Knots	60	90	120	150	180
Min:Sec	5:06	3:24	2:33	2:02	1:42

HINZZ INT
I-SGS 5.9

04°

40 ✖ 250

250

A horizontal beam is shown with a central support labeled 'B'. The beam is divided into two equal segments by the support. The left end is labeled 'A' and the right end is labeled 'C'. The support 'B' is located at the midpoint between 'A' and 'C'.

(500-1)

1540-1

719 (800-1)

C CIRCLING

1400-1

	154
--	-----

0-1	
-----	--

540-2

1620-2½

SOUTH ST PAUL MUNI/RICHARD E FLEMING ELD (SGS)

44°51'N-93°02'W

LOC RWY 34