

ILS Z or LOC Z RWY 20R
FAIRBANKS INTL (FAI) (PAFA)

MISSED APPROACH: Climb to 1100 then climbing left turn to 3000 on FAI VORTAC R-107 to KRNL/FAI VORTAC 13 DME and hold.

MALSR