


PLEASANTON MUNI (PEZ)
PLEASANTON, TEXAS

PLEASANTON, TEXAS

SAN ANTONIO DEP CON
125.7 290.225
CLINC DEL
121.375

RNAV 1 - DME/DME IRU or GPS.	
RADAR required.	

**TOP ALTITUDE:
ASSIGNED BY ATC**



DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAY 16: Climb on heading 157° or as assigned by ATC, for vectors to WRKIT, thence . . .
TAKEOFF RUNWAY 34: Climb on heading 337° or as assigned by ATC, for vectors to WRKIT, thence . . .
... on track 080° to CHURN, then on track 085° to SNIDR, then on transition. Maintain ATC assigned altitude.

BLUMS TRANSITION (SNIDR1.BLUMS)
CAAGE TRANSITION (SNIDR1.CAAGE)
FFSH TRANSITION (SNIDR1.FFSH)
MOLL TRANSITION (SNIDR1.MOLL)
SEEDS TRANSITION (SNIDR1.SEEDS)
WEMAR TRANSITION (SNIDR1.WEMAR)
WHAEL TRANSITION (SNIDR1.WHAEL)
WYLSN TRANSITION (SNIDR1.WYLSN)

Note: Chart not to scale.

SC-3, 18 APR 2024 to 16 MAY 2024

SNIDR ONE DEPARTURE (RNAV)
(SNIDR1.SNIDR) 25JAN24

PLEASANTON, TEXAS
PLEASANTON MUNI (PEZ)