

WAAS CH 78421 W23B	APP CRS 230°	Rwy Idg TDZE 743 Apt Elev 744
--	------------------------	---

RNAV (GPS) RWY 23R


RICKENBACKER INTL (LCK)

RNP APCH.

⚠ Baro-VNAV NA when using John Glenn Columbus Intl altimeter setting. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -16°C or above 54°C. Circling NA northwest of Rwy 5L-23R. VDP NA with John Glenn Columbus Intl altimeter setting. When local altimeter setting not received, use John Glenn Columbus Intl altimeter setting: increase LPV DA to 978 feet; increase LNAV/VNAV DA to 1041 feet and all visibilities to 1 SM; increase all MDAs 40 feet and Circling Cat D visibility ¼ SM.

MISSED APPROACH: Climb to 3000 direct COLMU and on track 177° to XUB VOR and hold.

ATIS 132.75	COLUMBUS APP CON 134.0 279.6	RICK TOWER 120.05 348.4	GND CON 125.275 275.8	CLNC DEL 125.275 275.8
-----------------------	--	-----------------------------------	---------------------------------	----------------------------------



ELEV **744** **D** TDZE **743**

3000

COLMU

tr 177°

XUB

VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 79).

4 NM Holding Pattern

* LNAV only.

HESLA

2400

230°

050°

3000

GP 3.00° TCH 55

1.3

3.7 NM

6.5 NM

CATEGORY	A	B	C	D
LPV DA	943-¾ 200 (200-¾)			
LNAV/VNAV DA	1006-⅞ 263 (300-⅞)			
LNAV MDA	1220-1	477 (500-1)	1220-1⅓ 477 (500-1⅓)	
CIRCLING	1240-1	496 (500-1)	1280-1½ 536 (600-1½)	1400-2 656 (700-2)

TWR 852

1190° X 130

1210° X 200

5L 5R

TDZ/CL Rwy 5R
REIL Rwy 23R
HIRL Rwy 5L-23R and 5R-23L