HOT SPOTS				
An "airport surface hot spot" is a location on an aerodrome movement area with a history or potential risk of collision or runway incursion, and where heightened attention by pilots/drivers is necessary.				
A "hot spot" is a runway safety related problem area on an airport that presents increased risk during surface opera- tions. Typically it is a complex or confusing taxiway/taxiway or taxiway/runway intersection. The area of increased risk has either a history of or potential for runway incursions or surface incidents, due to a variety of causes, such as but not limited to: airport layout, traffic flow, airport marking, signage and lighting, situational awareness, and training. Hot spots are depicted on airport diagrams as open circles or ellipses designated as "HS 1", "HS 2", etc. and tabulat- ed in the list below with a brief description of each hot spot. Hot spots will remain charted on airport diagrams until such time the increased risk has been reduced or eliminated.				
CITY/AIRPORT	HOT SPOT	DESCRIPTION*		
ALAMOGORDO, NM				
HOLLOMAN AFB (HMN)	HS1 HS2	Twy R, Twy G, and Twy L have multiple hold lines for Rwy 07-25 and Rwy 04-22. Contact tower if confused or lost. Hold line on Twy /EOR A and Twy/EOR H have multiple POV		
	HS3	access roads, possibility of high vehicle traffic.		
	HS4	Hold line on Twy /EOR B and Twy C for Rwy 07-25 have multiple POV access roads, possibility of high vehicle traffic. Multiple hold lines at intersecting rwys. Landing/departing aircraft disregard hold lines, taxiing aircraft contact tower prior to crossing hold lines.		
	HS5	Multiple hold lines where rwys intersect. Hold line also at Twy D. Contact tower if confused or lost.		
	HS6	POV crossing controlled by tower. Hold line located on each side of Rwy 07-25. Possibility of high vehicular traffic.		
ALBUQUERQUE, NM ALBUQUERQUE INTL				
SUNPORT (ABQ)	HS 1 HS 2 HS 3	Hold Position Marking on Twy E1 for Rwy 08. Complex int at Twy F, Twy C, Twy G. Twy G and Rwy 03-21 Twy E5 permanently closed. Twy E int with Rwy 03-21, Twy H, and Hot Pad 2.		
ASPEN, CO ASPEN-PITKIN COUNTY/				
SARDY FLD (ASE)	HS 1 HS 2	Twy A2. Short taxi distance from ramp to rwy. CAUTION: High tfc intxn - acft rtnely hold short of Twy A4 on Twy A when indb to trml or general aviation ramp.		
	HS 3	Rwy 33 and Twy A9. Non-typical location for rwy holding position marking.		
COLORADO SPRINGS, CO CITY OF COLORADO				
SPRINGS (COS)	HS 1 HS 2 HS 3	The apch ends of Rwy 13 and Rwy 17R; and Twy A1. Twy A4 and Twy G at Rwy 17R-35L. Int of Twy E4, Twy G, Twy H and Twy E.		
DENVER, CO	HS 4	Apch ends of Rwy 35R and Rwy 35L.		
CENTENNIAL (APA)	HS 1 HS 2 HS 3 HS 4	Rwy 17L at Twy A1. Twy A, Twy A8, Twy A9 and Twy C1 congested INT. Rwy 10 hold line on Twy C1 is located 30 ft from edge of ramp. Hold Short Line for Rwy 17L-35R on Twy B8.		
DENVER, CO DENVER INTL (DEN)	HS 1	Twy ED at Twy M. Close proximity to Rwy 17R apch.		

20 FEB 2025 to 20 MAR 2025

(SEE CONTINUATION PAGE FOR MORE LISTINGS)

20 FEB 2025 to 20 MAR 2025

		HOT SPOTS
		(CONTINUED)
CITY/AIRPORT HC	OT SPOT	DESCRIPTION*
DENVER, CO ROCKY MOUNTAIN METRO (BJC)	HS 1 HS 2 HS 3	Frequent helicopter operations. Multiple hold lines in close proximity. Hold line on Twy B south of Rwy 12R-30L is prior to Twy D. Pilots taxiing south on Twy D and instructed to cross Rwy 03 mistakenly turn onto Rwy 03. Pilots taxiing on Rwy 03 and instructed to hold short of Rwy 12R/30L fail to hold short. Hold line immediately after turn onto Rwy 03.
EAGLE, CO EAGLE COUNTY RGNL (EGE)	HS 1	High density parking area.
GRAND JUNCTION, CO GRAND JUNCTION RGNL (GJT) ROSWELL, NM ROSWELL AIR CENTER	HS 1	Rwy 22 and Rwy 29 close proximity, wrong rwy departure risk.
(ROW)	HS 1	Twy A, Twy B, and Twy D form a complex int in close proximity to Rwy 03-21.

20 FEB 2025 to 20 MAR 2025

*See appropriate Chart Supplement HOT SPOT table for additional information.