




ILS RWY 5 (CAT II)
FORT WAYNE INTL (FWA)

MISSED APPROACH: Climb to 1300 then climbing right turn to 3000 on FWA R-134 to OSBER INT/FWA 22 DME and hold.



CATEGORY	A	B	C	D
S-ILS 5	RA 106/12 100 DA 915			

CATEGORY II ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED



EC-2, 17 APR 2025 to 15 MAY 2025