

LOC/DME I-DJK

109.95

Chan 36 (Y)

APP CRS

022°

Rwy Idg

7026

TDZE

913

Apt Elev

913

ILS or LOC RWY 2

DE KALB TAYLOR MUNI (DKB)

RADAR required for procedure entry. DME or RADAR required.

VDP NA with Aurora altimeter setting. When local altimeter setting not received, use Aurora altimeter setting and increase DA to 1174 feet and all MDA 80 feet; CETAN fix minimums increase Circling Cat C and D visibility ¼ SM. For inop ALS, increase S-ILS 2 all Cats visibility to ¾ SM. CETAN fix minimums: For inop ALS, increase S-LOC 2 Cat C and D visibility to 1 SM.

MALSR

MISSED APPROACH:

Climb to 3000 on heading 022° and OBK VOR/DME R-254 to YEARN Int and hold.

AWOS-3

119.075

CHICAGO APP CON

133.5 349.0

UNICOM

122.7 (CTAF) 0

MSA DPA 25 NM

2600

113.0 OBK R-254 Chan 77

1185 A

1019 ±

1050 ±

1237 A

1366 A

CETAN I-DJK 4.3

JINYO I-DJK 6.7 RADAR

2700 022° (6.1)

(IF) TUGBY I-DJK 12.8 RADAR

202°

LOCALIZER 109.95 I-DJK Chan 36 (Y)

MISSED APCH FIX

R-318

113.0 OBK R-254 Chan 77

074°

254°

108.4 DPA Chan 21

YEARN

DUPAGE 108.4 DPA Chan 21

1480 A

VGSI and ILS glidepath not coincident (VGSI Angle 3.00/TCH 53).

3000

hdg 022°

OBK R-254

YEARN

TUGBY I-DJK 12.8 RADAR

JINYO I-DJK 6.7 RADAR

CETAN I-DJK 4.3

I-DJK 2.4

I-DJK 1.3

2700

022°

2700

1900

GS 3.00° TCH 55

6.1 NM

2.4 NM

1.9

1.1

CATEGORY	A	B	C	D
S-ILS 2	1113-½		200 (200-½)	
S-LOC 2	1900-¾ 987 (1000-¾)	1900-1 987 (1000-1)	1900-2½	987 (1000-2½)
CIRCLING	1900-1¼ 987 (1000-1¼)	1900-1½ 987 (1000-1½)	1900-3	987 (1000-3)
CETAN FIX MINIMUMS (DME REQUIRED)				
S-LOC 2	1280-½ 367 (400-½)	1280-⅝ 367 (400-⅝)		
CIRCLING	1360-1 447 (500-1)	1500-1 587 (600-1)	1600-2 687 (700-2)	1740-2¾ 827 (900-2¾)

ELEV 913

TDZE 913

MIRL Rwy 2-20

MIRL Rwy 9-27

REIL Rwy 9, 20 and 27

4201 X 75

7026 X 100

022°

DE KALB, ILLINOIS

Orig-F 30DEC21

41°56'N-88°42'W

DE KALB TAYLOR MUNI (DKB)

ILS or LOC RWY 2