


APP CRS	Rwy Ldg	10114
281°	TDZE	815
	Apt Elev	815

RNAV (RNP) Z RWY 28L

JOHN GLENN COLUMBUS INTL (CMH)

RNP AR APCH.	MALSR	MISSED APPROACH: Climb to 1400 then climbing left turn to 3000 direct BOUTN LOM and hold.
For uncompensated Baro-VNAV systems, procedure NA below -19°C or above 54°C. For inop ALS, increase RNP 0.30 all Cats visibility to 1½ SM. Simultaneous approach authorized.		

D-ATIS 124.6	COLUMBUS APP CON 125.95 371.975	COLUMBUS TOWER 132.7 257.8	GND CON 121.9 348.6
-----------------	------------------------------------	-------------------------------	------------------------



ELEV 815	D	TDZE 815
----------	---	----------

