


ILS RWY 28R (CAT II & III)
CHICAGO O'HARE INTL (ORD)

MISSED APPROACH: Climb to 1100 then climbing left turn to 4000 on heading 215° and DPA VOR/DME R-082 to DPA VOR/DME and hold.




MISSED APCH FIX
DUPAGE
DPA 
114.55
Chan 92(Y) 
B-248-068°  048°

ELEV 680	D	TDZE 651
----------	----------	----------



HIRL all Rwys
TDZ/CL all Rwys except 4L



CATEGORY II & III ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED