

LOC/DME I-GYH 108.3 Chan 20	APP CRS 047°	Rwy Ldg TDZE 956 Apt Elev 956	ILS or LOC RWY 5 DONALDSON FLD (GYH)
---	------------------------	---	---

RNP APCH - GPS.
DME or RADAR required.

▼ VDP NA when using Greer altimeter setting. When local altimeter setting not received, use Greer altimeter setting and increase S-ILS 5 DA to 1185 feet; increase all MDAs 40 feet and S-LOC 5 visibility Cats C, D, E ½ SM. For inop ALS, increase S-ILS 5 Cat E visibility to ¾ SM and increase S-LOC 5 Cat E visibility to 1 ½ SM. For inop ALS when using Greer altimeter setting, increase S-ILS 5 Cat E visibility to ¾ SM and increase S-LOC 5 Cat E visibility to 1 ½ SM. DME required when GSP App Can closed.

MALSR

MISSED APPROACH:
Climbing left turn to 3000 direct NINYI and hold.

ATIS 127.325	GREER APP CON★ 118.8 270.275	DONALDSON TOWER★ 133.325 (CTAF) 269.25	GND CON 121.4	UNICOM 122.7
------------------------	--	--	-------------------------	------------------------

MISSED APCH FIX

4 NM
227°
047°
NINYI

LOCALIZER 108.3
I-GYH
Chan 20

Greenville
Downtown

JUDKY
521 GM ==•

GASRR
I-GYH 6.5
RADAR

1202

2600
047°
(7.2)

(IF/IAF)
NINYI
I-GYH 13.7
RADAR
IRQ 56.4

6000
3000
HOLD

227°
047°
1 min

R-344

3000 NoPT
344° (18.4)

(IAF)
DEANS
IRQ 38

3000
344°
(38)

COLLIERS
113.9 IRQ
Chan 86

ALTERNATE MISSED APCH FIX

SPARTAN
SPA
115.7
Chan 104

014°
194°
R-194

MSA GM 25 NM
5300
220°
3000
040°

ELEV 956

TDZE 956

One Minute Holding Pattern

NINYI I-GYH 13.7 RADAR

6000
3000

227°
047°

GS 3.00°
TCH 52

2600

2600

7.2 NM

4 NM

1 NM

VGSI and ILS glidepath not coincident (VGSI Angle 3.22/TCH 56).

GASRR I-GYH 6.5 RADAR

I-GYH 2.4

I-GYH 1.5

3000 NINYI I-GYH 13.7

0.3% DOWN

8000 X 150

0.6% UP

TWR

047°

HIRL Rwy 5-23

FAF to MAP 5 NM

Knots	60	90	120	150	180
Min:Sec	5:00	3:20	2:30	2:00	1:40

GREENVILLE, SOUTH CAROLINA

Amdt 6 23FEB23

34°46'N-82°23'W

DONALDSON FLD (GYH)

ILS or LOC RWY 5

SE-2, 27 NOV 2025 to 25 DEC 2025

SE-2, 27 NOV 2025 to 25 DEC 2025