

WAAS CH 48920 W30A	APP CRS 305°	Rwy Ldg 5499 TDZE 3653 Apt Elev 3657
--	------------------------	---

RNAV (GPS) RWY 30

RENNER FLD/GOODLAND MUNI (GLD)

RNP APCH.



Circling NA to Rwy 17 and 35. Circling NA south of Rwy 5 and 30. Rwy 30 helicopter visibility reduction below $\frac{3}{4}$ SM NA. Inop table does not apply. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -22°C or above 54°C.

MALSR





MISSED APPROACH: Climb to 5600
direct DAKKA and hold.

ASOS
121.025

DENVER CENTER
132.7 226.675

UNICOM
122.8 (CTAF) **L**

Procedure NA for arrival on GLD VORTAC
airway radials 084 CW 140.





MISSED APCH FIX



ELEV 3657

TDZE 3653

REIL Rwy 12 MIRL Rwy 5-23 and 12-30 

RNAV (GPS) RWY 30