


APP CRS	Rwy Ldg	7614
306°	TDZE	57
	Apt Elev	62

RNAV (RNP) Z RWY 30L


NORMAN Y MINETA SAN JOSE INTL (SJC)

RNP AR APCH. ▼ For uncompensated Baro-VNAV systems, procedure NA below 1°C or above 54°C. For inop ALS, increase RNP 0.10 all Cats visibility to RVR 5500 and increase RNP 0.30 all Cats visibility to 1½ SM.	MALSR AS MISSED APPROACH: Climb to 2000 on track 306° to ARTAQ and hold.
--	--

D-ATIS 126.95	NORCAL APP CON 120.1 290.25	SAN JOSE TOWER★ 124.0 (CTAF) 0 257.6	GND CON 121.7	UNICOM 122.95
------------------	--------------------------------	---	------------------	------------------



ELEV	62	D	TDZE	57
------	----	---	------	----



2000 tr 306°	ARTAQ	VGSI and RNAV glidepath not coincident (VGSI Angle 3.00/TCH 70).		WOXAR
See planview for multiple IF locations.				
RW30L				
306°				
4.7 NM				
GP 3.00° TCH 54				
CATEGORY	A	B	C	D
RNP 0.10 DA	430/35 373 (400-½)			
RNP 0.20 DA	464/40 407 (500-¾)			
RNP 0.30 DA	541/50 484 (500-1)			
AUTHORIZATION REQUIRED				