




LOC/DME I-DQQ 111.9 Chan 56	APP CRS 173°	Rwy Ldg TDZE 5326 Apt Elev 5434
---	------------------------	---

ILS or LOC RWY 16R
DENVER INTL (DEN)

▼ For inoperative MALSR, increase S-LOC Cat C/D visibility to RVR 4500. Simultaneous approach authorized with Rwy 17L and 17R. DME required.	MALSR 	MISSED APPROACH: Climb to 5900 then climbing right turn to 12000 on heading 218° and on FGF VORTAC R-254 to BREWS/FQF 26 DME and hold.
---	------------------	---

D-ATIS 125.6 379.9	DENVER APP CON 119.3 307.3 (N) 120.35 379.3 (S)	DENVER TOWER 135.3 351.95	GND CON 121.35 379.175 (W) 121.85 377.1 (E)
-------------------------------------	--	--	--



RADAR or GPS REQUIRED

