



LOC/DME I-BDL 111.1 Chan 48	APP CRS 058°	Rwy Ldg TDZE 173 Apt Elev 173	ILS RWY 6 (CAT II & III) BRADLEY INTL (BDL)
---	------------------------	---	--

RADAR required for procedure entry.	ALSF-2 	MISSED APPROACH: Climb to 4000 then left turn direct BAF VORTAC and hold.
CAT II: RVR 1000 authorized with specific OPSPEC, MSPEC or LOA approval and use of autoland or HUD to touchdown.		

D-ATIS 118.15	BRADLEY APP CON 123.95 290.55 (061°-240°) 125.35 281.5 (241°-060°)	BRADLEY TOWER 120.3 351.8	GND CON 121.9 348.6
-------------------------	--	-------------------------------------	-------------------------------



ELEV 173	D	TDZE 173
----------	---	----------



VGSI and ILS glidepath not coincident (VGSI Angle 3.00/TCH 71).				4000	BAF
One Minute Holding Pattern					
PENNA INT I-BDL [12.8]				JANID INT I-BDL [9.9]	
7000 3000 238° 058° 058° 2400 1800				HUNEE INT I-BDL [6.9]	
GS 3.00° TCH 54				1800	
3 NM 3 NM 4.9 NM 1052'					
CATEGORY	A	B	C	D	
S-ILS 6	CAT II RA 101/12 100 DA 273				
S-ILS 6	CAT III RVR 06				

CATEGORY II & III ILS-SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED