


APP CRS	Rwy Ldg	10114
101°	TDZE	809
	Apt Elev	815


RNAV (RNP) Z RWY 10R
JOHN GLENN COLUMBUS INTL (CMH)

RNP AR APCH - GPS. Authorization required. From CASER or TOYON: RF.	MALSR 	MISSED APPROACH: Climb to 1400 then climbing right turn to 3000 direct BOUTN LOM and hold.


D-ATIS 124.6	COLUMBUS APP CON 125.95 371.975	COLUMBUS TOWER 132.7 257.8	GND CON 121.9 348.6
-----------------	------------------------------------	-------------------------------	------------------------



ELEV 815	D	TDZE 809
----------	----------	----------



TDZL/RCLS Rwy 10R and 28L
HIRL Rwy 10R-28L and 10L-28R



AUTHORIZATION REQUIRED