

LOC/DME I-PWM 109.9 Chan 36	APP CRS 110°	Rwy Ldg 7200 TDZE 76 Apt Elev 76
---	------------------------	---

ILS RWY 11 (CAT II & III)
PORTLAND INTL JETPORT (PWM)




Procedure NA when control tower closed.



ALSF-2

MISSED APPROACH: Climb to 600 then climbing right turn to 3000 direct ENE VOR/DME and hold.

ATIS 119.05	PORTLAND APP CON ★ 119.75 269.35	PORTLAND TOWER ★ 120.9 0 (CTAF) 257.8	GND CON 121.9	UNICOM 122.95
-----------------------	--	---	-------------------------	-------------------------



BUXTO I-PWM 10.6 RADAR

MAINA INT I-PWM 6.6

IM 177

GS 3.00° TCH 51

4 NM 5.3 NM 10.7 NM

CATEGORY	A	B	C	D
S-ILS 11	CAT II RA 108/12 100 DA 176			
S-ILS 11	CAT III RVR 06			

CATEGORY II & III ILS-SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED

ELEV 76 TDZE 76

TDZL/RCLS Rwy 11 1

MIRL Rwy 18-36 1

HIRL Rwy 11-29 1

REIL Rwy 18 and 36 1

NE-1, 22 JAN 2026 to 19 FEB 2026