

25331

ILS or LOC RWY 36L
ORLANDO INTL (MCO)

MISSED APPROACH: Climb to 500 then climbing left turn to 3000 on heading 340° and ORL VORTAC R-248 to DNMR/ORL 6 DME and hold, continue climb-in-hold 3000.

Simultaneous approach authorized.

Figure 1: Example of a typical ILS chart. The chart displays the ILS glidepath (3.00° TCH 51) and the VGSI glidepath (3.00° TCH 69). The chart includes a table of ILS data:

CATEGORY	A	B	C	D
S-ILS 36L	293/40	200 (200-3/4)		
S-LOC 36L	440/55	347 (400-1)		
CIRCLING	740-1	644 (700-1)	740-1 3/4 644 (700-1 3/4)	740-2 644 (700-2)

ORLANDO INTL (MCO)

ILS or LOC RWY 36L

SE-3, 22 JAN 2026 to 19 FEB 2026