


LOC/DME I-HCV	APP CRS	Rwy Ldg	6215
110.3	052°	TDZE	947
Chan 40		Apt Elev	947

ILS or LOC RWY 5

WEST VIRGINIA INTL YEAGER (CRW)

Autopilot coupled approach NA below 1300.		MISSED APPROACH: Climb to 1800 then climbing left turn to 3500 direct HVQ VOR/DME and hold.	
ATIS 127.6	CHARLESTON APP CON 124.1 269.125	CHARLESTON TOWER 125.7 257.8	GND CON 121.8 348.6



One Minute Holding Pattern 5400 3500 ←232° 052°→ GS 3.00° TCH 56 SHOAL INT I-HCV 11.9 RADAR KANCO INT I-HCV 6 RADAR ZEVRU INT I-HCV 2.1 I-HCV DME ANTENNA I-HCV UCIYUZ I-HCV 0.1 1800 ↑ 3500 ↶ HVQ ◻ 2900 2900 1640 1 NM 1 NM 0.1 5.9 NM 3.9 NM 1 NM 1 NM 0.1						ELEV 947 D TDZE 947 ↻ <					
--	--	--	--	--	--	--	--	--	--	--	--