



|                                                 |                        |                                                               |
|-------------------------------------------------|------------------------|---------------------------------------------------------------|
| LOC/DME I-LLM<br><b>111.7</b><br>Chan <b>54</b> | APP CRS<br><b>317°</b> | Rwy Ldg <b>7120</b><br>TDZE <b>102</b><br>Apt Elev <b>107</b> |
|-------------------------------------------------|------------------------|---------------------------------------------------------------|

ILS or LOC RWY 32  
MC ALLEN INTL (MF'E)

|                                                                                                                                                                                                |                                       |                                                       |                         |                         |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------|-------------------------------------------------------|-------------------------|-------------------------|
| <b>⚠</b> Circling NA northeast of Rwy 14-32. ADF and DME or Radar required. When local altimeter setting not received, use Weslaco altimeter setting: increase all DA 39 feet and MDA 40 feet. |                                       | MISSED APPROACH: Climb to 2100 direct MF LOM and hold |                         |                         |
| ATIS<br><b>128.5</b>                                                                                                                                                                           | VALLEY APP CON<br><b>126.55 377.2</b> | MC ALLEN TOWER ★<br><b>118.5 (CTAF) 0 256.9</b>       | GND CON<br><b>121.8</b> | UNICOM<br><b>122.95</b> |

DME or RADAR REQUIRED



|                     |                                                                 |                                            |                              |                              |                            |                 |
|---------------------|-----------------------------------------------------------------|--------------------------------------------|------------------------------|------------------------------|----------------------------|-----------------|
| 2100<br>↑<br>MF<br> | VGSI and ILS glidepath not coincident (VGSI Angle 3.00/TCH 53). |                                            | GASHS I-LLM 5<br>RADAR       |                              | One Minute Holding Pattern |                 |
| *LOC only           | OYICU I-LLM 1.2                                                 | 1800                                       |                              | 137°                         | 2100                       |                 |
|                     |                                                                 | 317°                                       | 1800                         | 317°                         |                            | GS 3.00° TCH 50 |
|                     |                                                                 | *600 when using Weslaco alimenter setting. |                              |                              |                            |                 |
|                     | 1.4 NM                                                          | 3.8 NM                                     |                              |                              |                            |                 |
| CATEGORY            | A                                                               | B                                          | C                            | D                            |                            |                 |
| S-ILS 32            | 302-3/4                                                         |                                            | 200 (200-3/4)                |                              |                            |                 |
| S-LOC 32            | 560-1                                                           | 458 (500-1)                                | 560-1 3/8                    | 458 (500-1 3/8)              |                            |                 |
| CIRCLING            | 580-1                                                           | 473 (500-1)                                | 580-1 1/2<br>473 (500-1 1/2) | 800-2 1/4<br>693 (700-2 1/4) |                            |                 |
| OYICU FIX MINIMUMS  |                                                                 |                                            |                              |                              |                            |                 |
| S-LOC 32            | 440-1                                                           |                                            | 338 (400-1)                  |                              |                            |                 |
| CIRCLING            | 580-1                                                           | 473 (500-1)                                | 580-1 1/2<br>473 (500-1 1/2) | 800-2 1/4<br>693 (700-2 1/4) |                            |                 |