

ILS RWY 35R (CAT II & III)
DENVER INTL (DEN)

- MISSED APPROACH:** Climb to 5800 then climbing right turn to 10000 on heading 048° and on GLL VORTAC R-136 to CEDUK/GLL 16 DME and hold.



RADAR or GPS REQUIRED

Diagram illustrating an alternate missed approach for R-056. The diagram shows a flight path starting from a point labeled "117.9 DEN" and "R-056". The path turns right at a 236-degree angle and then left at a 056-degree angle. A dashed line indicates the missed approach path. The diagram is labeled "WITNE DEN" and "25.6".



CATEGORY II & III ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED