

NANDR THREE DEPARTURE (RNAV)


GRAND PRAIRIE MUNI (GPM)

GRAND PRAIRIE, TEXAS

LONE STAR DEP CON
135.975 379.9
GND CON
121.15
GRAND PRAIRIE TOWER ★
128.55 (CTAF)

RNAV 1 - DME/DME/IRU or GPS.
RADAR required.

TOP ALTITUDE: ASSIGNED BY ATC



(CONTINUED ON FOLLOWING PAGE)

NANDR THREE DEPARTURE (RNAV)
(NANDR3.NANDR) 17APR25

GRAND PRAIRIE, TEXAS
GRAND PRAIRIE MUNI (GPM)

▼

DEPARTURE ROUTE DESCRIPTION

TAKOFF RUNWAY 18: Climb on heading 192° to 2500 before proceeding on course or as assigned by ATC, thence. . .

TAKOFF RUNWAY 36: Climb on heading 357° to 1400 before turning southbound or as assigned by ATC, thence. . .

. . .expect RADAR vectors to cross CUZNO at or above 3000, then on track 357° to cross NANDR at or below 13000, then on assigned transition.

EAKER TRANSITION (NANDR3.EAKER)

MC ALESTER TRANSITION (NANDR3.MLC)

OKMULGEE TRANSITION (NANDR3.OKM)

ROLLS TRANSITION (NANDR3.ROLLS)

TULSA TRANSITION (NANDR3.TUL)

WILL ROGERS TRANSITION (NANDR3.IRW)

ZEMMA TRANSITION (NANDR3.ZEMMA)