

## HI-TACAN Z RWY 26

[USAF]

SEYMOUR JOHNSON AFB (KGSB)



▼ \* When ALS inop, increase vis to 1 ¼ miles.  
\*\* Circling N of Rwy 8-26 not authorized.

ALSF-1

**MISSED APPROACH:** Climb to 2200 via GSB R-261 to TULME and hold.

[illegible]

397



EMERG SAFE ALT 100 NM 3700

GOLDSBORO, NORTH CAROLINA

35°20'N-77°58'W

SEYMOUR JOHNSON AFB (KGSB)

Amdt 8 03NOV22

## HI-TACAN Z RWY 26