


VORTAC RIC 114.1 Chan 88	APP CRS 041°	Rwy Ldg TDZE 162 Apt Elev 167	6607
--	------------------------	---	-------------

VOR RWY 2


RICHMOND INTL (RIC)

▼ Rwy 2 helicopter visibility reduction below 3/4 SM NA. For inop ALS, increase S-2 Cat A/B visibility to 1 SM, and Cat C/D to 1 1/2 SM.	MALSR 	MISSED APPROACH: Climbing left turn to 2000 on RIC VORTAC R-018 to EPICS INT/ RIC 17.3 DME and hold.
---	-----------	--


ATIS 119.15 263.025	POTOMAC APP CON 126.4 282.375 (001°-185°) 126.75 307.2 (186°-360°)	RICHMOND TOWER 121.1 257.8	GND CON 121.9 348.6
-------------------------------	--	---	-------------------------------



ELEV 167	D	TDZE 162
TDZ/CL Rwy 34		
HIRL Rws 2-20 and 16-34		
REIL Rwy 20		



FAF to MAP 6.1 NM					
Knots	60	90	120	150	180
Min:Sec	6:06	4:04	3:03	2:26	2:02



CATEGORY	A	B	C	D
S-2	640-3/4	478 (500-3/4)	640-1	478 (500-1)
CIRCLING	660-1	493 (500-1)	700-1 1/2 533 (600-1 1/2)	720-2 553 (600-2)