

TACAN RWY 19

TACAN NCA
Chan 101

APCH CRS
199°

Rwy Idg
4789

TDZE
23

Arpt Elev
26

[USN] NEW RIVER MCAS (MCCUTCHEON FLD) (KNCA)

RADAR required

MISSED APPROACH: Climbing left turn to 1500 intercept NCA TACAN R-042 direct MARVL (R-042/8 DME) and hold.

ATIS ★
288.325

CHERRY POINT APP CON
119.35 377.175

TOWER ★
134.95(CTAF) 0★ 360.2

GND CON
121.8 254.275

CLNC DEL
269.25

ASR/PAR

135

CAUTION: Intmd segment length 3 NM less than CAT AB minimum 5 NM; CAT CD minimum 6 NM.

NEW RIVER
Chan 101 NCA

MSA NCA 2.5 NM
3100
2100
180°
270°

EMERG SAFE ALT 100 NM 3400

1500
NCA
R-042

MARVL
NCA
B

VGSI and descent angles not coincident
(VGSI Angle 3.00/TCH 41).

NCA TACAN

POSTY
NCA 0.3

NCA 1.6

TUDSE
NCA 2.1

NAPIE
NCA 5

ZUBIL
NCA 8

1500

560

199°

2.95°

TCH 50

CATEGORY	A	B	C	D
S-19	440-1 417 (500-1)	440-1 417 (500-1)	440-1 417 (500-1)	440-1 417 (500-1)
CIRCLING	500-1 474 (500-1)	500-1 474 (500-1)	700-2 674 (700-2)	700-2 674 (700-2)

HIRL all rwys

ELEV 26

TDZE 23

JACKSONVILLE, NORTH CAROLINA

34° 43' N-77° 26' W

NEW RIVER MCAS (MCCUTCHEON FLD) (KNCA)

Amtd 5 10JUL25

TACAN RWY 19