

APP CRS
095°

Rwy Idg **4498**
TDZE **161**
Apt Elev **160**

RNAV (GPS) RWY 9

WILSON INDUSTRIAL AIR CENTER (W03)

▼

NA

DME/DME RNP-0.3 NA. Procedure NA at night. Visibility reduction by helicopters NA. Obtain local altimeter setting on CTAF; when not received use Rocky Mount altimeter setting.


MISSED APPROACH: Climb to 2500 direct ROGCO then left turn via 002° track to FEBEL and hold.

WASHINGTON CENTER

123.85 279.65

UNICOM

123.0 (CTAF) 0



ELEV 160		TDZE 161	
4 NM Holding Pattern CATNU HAGIB LASPE NUDKE 2 NM to RW09 RW09 FEBEL 095° to RW09 002° tr 2700 275° 095° 2300 2100 820 3.05° TCH 40 4 NM 2 NM 3.9 NM 2 NM			
CATEGORY	A	B	D
RNAV MDA	560-1 399 (400-1)		560-1¼ 399 (400-1¼)
CIRCLING	660-1 500 (500-1)	780-1¾ 620 (700-1¾)	780-2 620 (700-2)
ROCKY MOUNT ALTIMETER SETTING MINIMUMS			
RNAV MDA	580-1 419 (500-1)		580-1¼ 419 (500-1¼)
CIRCLING	680-1 520 (600-1)	800-1¾ 640 (700-1¾)	800-2 640 (700-2)

REIL Rwy 3 and 21 0

MIRL Rwy 3-21 0