


NANDR THREE DEPARTURE (RNAV)

LONE STAR DEP CON
125.2 343.65 (Rwy 18)
124.3 282.275 (Rwy 36)

RNAV 1 - DME/DME/IRU or GPS.
RADAR required.

**TOP ALTITUDE:
ASSIGNED BY ATC**



SC-2, 19 MAR 2026 to 16 APR 2026

SC-2, 19 MAR 2026 to 16 APR 2026

NOTE: Chart not to scale.

(CONTINUED ON FOLLOWING PAGE)

NANDR THREE DEPARTURE (RNAV)

(NANDR3.NANDR) 17APR25

NANDR THREE DEPARTURE (RNAV)



DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAY 18: Climb on heading 178° or as assigned by ATC, thence. . .
TAKEOFF RUNWAY 36: Climb on heading 358° or as assigned by ATC, thence. . .

. . . expect RADAR vectors to cross CUZNO at or above 3000, then on track 357°
to cross NANDR at or below 13000, then on assigned transition.

- EAKER TRANSITION (NANDR3.EAKER)
- MC ALESTER TRANSITION (NANDR3.MLC)
- OKMULGEE TRANSITION (NANDR3.OKM)
- ROLLS TRANSITION (NANDR3.ROLLS)
- TULSA TRANSITION (NANDR3.TUL)
- WILL ROGERS TRANSITION (NANDR3.IRW)
- ZEMMA TRANSITION (NANDR3.ZEMMA)

SC-2, 19 MAR 2026 to 16 APR 2026

SC-2, 19 MAR 2026 to 16 APR 2026