


APP CRS	Rwy Ldg	8000
281°	TDZE	813
	Apt Elev	815

RNAV (RNP) Z RWY 28R


JOHN GLENN COLUMBUS INTL (CMH)

RNP AR APCH.	MALSR	MISSED APPROACH: Climb to 1400 then climbing right turn to 3000 to APE VORTAC and hold.
For uncompensated Baro-VNAV systems, procedure NA below -19°C or above 54°C. For map ALS, increase RNP 0.16 all Cats visibility to RVR 4500 and increase RNP 0.30 all Cats visibility to RVR 5500. Simultaneous approach authorized.		

D-ATIS 124.6	COLUMBUS APP CON 125.95 371.975	COLUMBUS TOWER 132.7 257.8	GND CON 121.9 348.6
-----------------	------------------------------------	-------------------------------	------------------------



ELEV 815	D	TDZE 813	See planview for multiple IF locations.
1400	3000	APE	



CATEGORY	A	B	C	D
RNP 0.16 DA	1129/24	316 (400-1/2)		
RNP 0.30 DA	1185/35	372 (400-5/8)		

TDZL/RCLS Rwy 10R-28L
HIRL Rwy 10R-28L and 10L-28R

AUTHORIZATION REQUIRED

EC-2, 09 JUL 2026 to 06 AUG 2026

EC-2, 09 JUL 2026 to 06 AUG 2026