

WAAS CH 40299 W10B	APP CRS 101°	Rwy Ldg TDZE Apt Elev	8000 815 815
--	------------------------	-----------------------------	---

RNAV (GPS) Y RWY 10L

JOHN GLENN COLUMBUS INTL (CMH)

RNP APCH

▼


▲

For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -19°C or above 54°C.
LNAV procedure NA during simultaneous operations. Use of FD or AP providing RNAV track guidance required during simultaneous operations. Simultaneous approach authorized. For inop ALS, increase LNAV Cat C/D visibility to 1½ SM.
RVR 1800 authorized with use of FD or AP or HUD to DA.

MALSR

MISSED APPROACH:
Climb to 1400 then climbing left turn to 3000 direct APE
VORTAC and hold.

D-ATIS 124.6	COLUMBUS APP CON 125.95 371.975	COLUMBUS TOWER 132.7 257.8	GND CON 121.9 348.6
------------------------	---	--------------------------------------	-------------------------------



4 NM Holding Pattern

FLANK

CCREW

SILKN

RW10L

GP 3.00° TCH 50

2300

1660

3.3 NM

2 NM

1.2 NM

1.3 NM

1400

3000

APE

* LNAV only.

CATEGORY	A	B	C	D
LPV DA #	1015/24		200 (200-½)	
LNAV/VNAV DA	1197/35		382 (400-⅝)	
LNAV MDA	1280/24 465 (500-½)		1280/50 465 (500-1)	
CIRCLING	1340-1 525 (600-1)		1520-2 705 (800-2) 1520-2¼ 705 (800-2¼)	

TDZL/RCLS Rwy 10R-28L
HIRL Rwy 10R-28L and 10L-28R

EC-2, 09 JUL 2026 to 06 AUG 2026

EC-2, 09 JUL 2026 to 06 AUG 2026