

RNAV (GPS) RWY 11
PORTLAND INTL JETPORT (PWM)

MISSED APPROACH: Climb to 3000 direct SAPPE and hold, continue climb-in-hold to 3000.

NE-1, 09 JUL 2026 to 06 AUG 2026

NE-1 09 JUL 2026 to 06 AUG 2026