

25331

ILS or LOC RWY 36L
ORLANDO INTL (MCO)

MISSED APPROACH: Climb to 500 then climbing left turn to 3000 on heading 340° and ORL VORTAC R-248 to DNMR/ORL 6 DME and hold. continue climb-in-hold 3000.

Simultaneous approach authorized.

Figure 1 illustrates a 3D visualization of the ILS and VGSIs. The diagram shows the runway (36R/36L) and the ILS/VGSIs. The ILS is shown as a dashed line with a 0.05° angle. The VGSIs are shown as solid lines with angles of 0.05° and 0.03°. The diagram includes labels for various navigation aids and distances, such as 0.9 NM, 1.1 NM, 2.6 NM, 4.4 NM, and 3.3 NM. It also shows the ILS and VGSIs for Runway 36L and Runway 36R.

ORLANDO INTL (MCO)

ILS or LOC RWY 36L

SE-3, 09 JUL 2026 to 06 AUG 2026