

ILS or LOC RWY 18L
HUNTSVILLE INTL-CARL T JONES FLD (HSV)

MISSED APPROACH: Climb to 2500 then climbing left turn to 4000 on heading 160° and VUZ R-011 to FEWER INT/VUZ 39.4 DME and hold.

MISSED APCH FIX

112.2 RQZ
R-187
Chan 59

FEWER VUZ [39.4]

11.4 VUZ
R-011
Chan 91

112.3 GAD
R-300
Chan 70

191°

011°

HOLD 5000 3000

ROCKET 112.2 RQZ Chan 59

(IF/IAF) BISBE INT RADAR

COTIN INT RADAR

DEBAY INT RADAR

FEKSO INT 741 ±

LOCALIZER 111.9 I-TVN

Caution numerous migratory bird flocks in area. Wildlife refuge area south of airport.

WHEELER NATIONAL WILDLIFE REFUGE

ALTERNATE MISSIED APCH FIX ENIKY RQZ [23.7]

112.2 RQZ
R-195
Chan 59

015°

195°

3000 294° (?)

R-294

185°

185° (4.8)

R-253

R-235

R-222

R-2104C
R-2104E

R-2104A
R-2104D

R-2104B

2500

2100

185° (2.4)

180°

360°

MSA RQZ 25 NM

[3700]

[3200]

FIEV 429

IDZF 609

34°38'N-86°47'W

ILS or LOC RWY 18L