

ILS or LOC RWY 36L
HUNTSVILLE INTL-CARL T JONES FLD (HSV)

MALSR

 

MISSED APPROACH: Climb to 1100 then climbing left turn to 3000 on heading 350° and RQZ R-261 to TANNE/RQZ 17.6 DME and hold.

TANNE
RQZ 17.6

081°
261°

R-261

ROCKET
112.2 RQZ
Chan 59

LOCALIZER 108.5
I-ELL 4.8
Chan 22

696 ±

HEREG
I-ELL 4.8
RADAR

CECAB
I-ELL 7.7
RADAR

WHEELER NATIONAL
WILDLIFE REFUGE

R-2104C

R-2104B

R-2104A

MSA RQZ 25 NM

3200 3700

180°
360°

CAUTION: Numerous migratory bird flocks in area.
Wildlife Refuge Area south of airport.

2400
005°
(7.1)

185°
1 min
005°
185°

HOLD
5000
3100

(IF/IAF)
BOSAC
I-ELL 14.8
RADAR

ELEV 629 TDZE 616

TDZL/RCLS Rwy 18R and 36L
HIRL Rwy 18L-36R and 18R-36L

18R 18L

ELEV 629 TDZE 616

TDZL/RCLS Rwy 18R and 36L
HIRL Rwy 18L-36R and 18R-36L

Knots	60	90	120	150	180
Min:Sec	6:42	4:28	3:21	2:41	2:14