

ENID, OKLAHOMA

VOR/DME or TACAN RWY 35C

VORTAC END 115.4 Chan 101	APCH CRS 349°	Rwy Idg TDZE 1294 Arpt Elev 1307
---	-------------------------	--

[USAF]

VANCE AFB (KEND)

RNAV or RADAR monitoring required for missed approach.


SALSF

MISSED APPROACH: Climb to 4000 on END VORTAC R-356 to FILE/15 DME and hold.

When ALS inop, increase RVR to 55, vis to 1 mile.





ATIS ★ 115.4 263.15	APP CON ★ 125.45 343.625 (E) 126.75 346.325 (W)	TOWER ★ 124.05 259.1	GND CON ★ 121.675 289.4
-------------------------------	---	--------------------------------	-----------------------------------



EMERG SAFE ALT 100 NM 4500

ELEV 1307	TDZE 1294
------------------	------------------



ENID, OKLAHOMA

36°20'N - 97°55'W

VANCE AFB (KEND)

Orig 06AUG26

VOR/DME or TACAN RWY 35C